

**2008 Historic Resource Survey  
North Side, City of Granbury**

**Property No.: 134  
703 East Moore**

Preservation Priority:

**Low**

*These properties have no association or unidentified association with history or historic context(s). They have been moderately to severely altered, losing their original character and architectural integrity. These resources usually do not meet National Register criteria or criteria to be designated as Recorded Texas Historic Landmarks.*

Construction Date:

**Circa 1930s to 1940s**



Resource Type/Subtype:

**Building/House**

Current Owner(s):

**Lanny Ray Parker**

Stylistic Influence:

**National Folk, massed, side-gabled**

Brief History:

Area(s) of Significance:

Description of Resource:

Frame construction, asbestos siding  
Gable roof, composition shingles  
Double-hung, aluminum and wood windows, 6/6  
Single-door primary entrance  
Gable roof porch, fabricated metal supports  
Center passage plan  
Pier and beam foundation  
One story, 1,070 square feet  
Shed/porch addition to east side of house

Integrity:

**Location, setting, feeling**

Possible Threats:

**None**

Existing Historical

Designations/Protections:

**Neglect**