

2008 Historic Resource Survey
North Side, City of Granbury
Property No.: 137
719 East Moore

Preservation Priority:

High—Contributes to Recommended Historic District
Recommended Historic Landmark/RTHL/National Register Listing

These are the most significant resources in the survey area and they contribute to local history or broader historical patterns and possess strong association with (a) historic context(s). High priority properties are outstanding or unique examples of architecture, engineering or crafted or vernacular design. These properties retain a high degree of architectural or physical integrity, having few alterations, or can be easily returned to their original character. High priority properties may meet one or more criteria for listing in the National Register of Historic Places; they are likely to qualify to be designated as Recorded Texas Historic Landmarks and City of Granbury Historic Landmarks.

Construction Date:

Circa 1960



Resource Type/Subtype:

Building/House

Current Owner(s):

Johnny and Betty Matthews

Stylistic Influence:

Ranch

Brief History:

According to Mr. Matthews, this house is two smaller frame houses joined together under one common roof with added limestone veneer. According to Frances Bird, the limestone work was done by Odell McReynolds.

Area(s) of Significance:

Architecture

Description of Resource:

Frame construction, limestone veneer
Gable roof, composition shingles
Double-hung and fixed, aluminum windows
Single door primary entrance
Hipped roof porch, box columns with limestone veneers
Rectangular plan
Pier and beam foundation
One story, 1,786 square feet
Limestone wall with old grindstone embedded in east side of west wall

Integrity:

Location, workmanship, setting, feeling, association

Possible Threats:

None

Existing Historical

Designations/Protections:

None