

Site #10

Priority M: (Contributed to local history or broader historical patterns, but alterations have diminished its integrity; is a good but typical example of architecture, engineering, or crafted design; is a good but altered illustration of a common local building form, architectural style or type.)

102 W. Doyle
Granbury
Hood County
Est. 1945

Historic Use: Residence

Present Use: Residence

Property Type: Vernacular House

Stylistic Influence: Minimal Traditional

History of Property: N/A

Areas of Significance (include justification):

Bibliography (include any oral history):

N/A

Surveyor: Diane Lock

Date Surveyed: 2001

Photo Data: Roll/Frame D1/24

Description of Building:

Location: Original Location

-Building faces north

-One story

-Frame house

-Weatherboard Siding Exterior Wall Surface

-Wood sash, double hung windows

-Single door primary entrance

-Hipped roof

-Composition shingles

